

1995 INTERNATIONAL 4900 | 1HTSDAAN45H616739





Specifications			
OD Miles	308386	Engine Make	International
Engine Model	DT466	Fuel Type	Diesel
Fuel Tanks	1 Alum	Fuel Capacity	50
Exhaust	Horizontal	Breathers	Single
Trans Make	Eaton	Trans Type	Manual
Trans Model	Unable to Verify	Trans Speed	5
Cruise Control	No	Wet Line	Yes
Axle Type	Single	Axle F Capacity	10,000
Axle R Capacity	22,000	GVWR	32,000
Frame Type	Steel	Suspension	Spring
Wheelbase	254	Brake Type	Air
Engine Brake	No	Air Cond	Yes
Interior Color	Gray	Exterior Color	Red
Heated Mirrors	No	Power Mirrors	No
High Back Seats	Driver Side Only	Passenger Seat	Stationary
APU	No	Bumper	Painted
Collision Avoidance	No		


Tires, Wheels & Brakes - Front Axle	
Left	Right
Tires/Wheels Good 295/75R22.5 11/32 Steel	Tires/Wheels Good 295/75R22.5 12/32 Steel
Brakes Covered	Brakes Covered

Tires, Wheels & Brakes - Rear Axles			
Left Outer	Left Inner	Right Inner	Right Outer
Tires/Wheels Good 295/75R22.5 15/32 Steel	Tires/Wheels Good 295/75R22.5 19/32 Steel	Tires/Wheels Good 295/75R22.5 18/32 Steel	Tires/Wheels Good 295/75R22.5 19/32 Steel
Brakes Covered	Brakes Covered	Brakes Covered	Brakes Covered

Observations			
Keys Present?	1 Sets	Oil Leaks?	Yes
Oil Milky?	No	Water Leaks?	No
Oil in Coolant?	No	Clutch Play?	No
Starts?	Yes	Cracked/Chipped Glass?	No
Lights Works?	Yes	Wipers Works?	Yes
Guages Works?	Yes	Air Horn Works?	NA
City Horn Works?	Yes	Active Fault Codes	NA

General Observation Notes	
5 speed transmission noted in specs could not be verified. GPS Installed In Place Of Diagnostic Port, Faulty Ignition Switch	

Deficiencies			
Issue #	Check	Comment	Photo
D1	Underbody	Engine Oil Leak	
D2	Exterior	Cracked And Bubbled Paint	
D3	Exterior	Surface Rust On Exterior Components	
D4	Mechanical	Manual Fuel Shutoff Handle Required To Stop Engine	
D5	Interior	Passenger Seat Extremely Worn	
D6	Interior	Drivers Seat Cracked/Worn	
D7	Exterior	Driver/Passenger Steps Rusted	
D8	Underbody	Undercarriage Extremely Rusted	
D9	Exterior	Flatbed Severely Corroded/Rusted	
D10	Exterior	Front Bumper Rusted	
D11	Interior	Exposed Wiring In Radio Compartment	



Videos	
Video 1	
Video 2	
Video 3	
Video 4	