2007 FORD F-750 | 3FRXF75627V515423

Specifications

ODI Miles:	130574	ECM Miles:	130244
Engine Hours:	10095	Engine Make:	CAT
Engine Model:	C7.1 2L	Engine HP:	213
Fuel Type:	Diesel	Fuel Tanks:	1 Plastic
Fuel Capacity:	50	Exhaust:	Horizontal
Breathers:	Single	Trans Make:	Allison
Trans Type:	Auto	Trans Model:	2000
Trans Speed:	6	Cruise Control:	Yes
Trans Gear:	N	Axle Type:	Single
Axle F Capacity:	12,000	Axle R Capacity:	21,000
GVWR:	33,000	Frame Type:	Steel
Suspension:	Spring	Wheelbase:	176
Brake Type:	Air	Engine Brake:	No
Air Cond:	Yes	Interior Color:	Gray
Exterior Color:	White	Heated Mirrors:	No
Fairings:	None	Power Mirrors:	No
High Back Seats:	Driver Side Only	Passenger Seat:	Stationary
Radio:	No	Bumper:	Chrome
Collision Assistance:	No		

Tires, Wheels & Brakes - Front Axle

Left		Right	
Tires/Wheels		**Tires/Wheels**	
Good		Good	
11R22.5		11R22.5	
11R22.5		11R22.5	
Steel		Steel	
Brakes		**Brakes**	
Covered		Covered	

Tires, Wheels & Brakes - Rear Axles

Left Outer	Left Inner	Right Inner	Right Outer
Tires/Wheels	**Tires/Wheels**	**Tires/Wheels**	**Tires/Wheels**
Good	Good	Good	Good
11R22.5	11R22.5	11R22.5	11R22.5
60%	18/32	24/32	19/32
Steel	Steel	Steel	Steel
Brakes	**Brakes**	**Brakes**	**Brakes**
Covered	Covered	Covered	Covered

Observations

Keys Present?	1 Sets	Oil Leaks?	No
Oil Wthy?	No	Water Leaks?	Yes
Oil in Coolant?	No	Clutch Play?	NA
Starts?	Yes	Cracked/Chipped Glass?	No
Lights Works?	Yes	Wipers Works?	Yes
Gauges Works?	Yes	Air Horn Works?	NA
Cfg Horn Works?	Yes	Active Fault Codes	Yes

General Observation Notes

Passenger front wheel seal shows indication of leaking. Sound of a possible air leak behind dash when pressing brake pedal.

Deficiencies

Issue #	Check	Comment	Photo
1	Interior	Drivers seat torn	
2	Interior	Dash is cracked and broken with missing blank covers	
3	Interior	Headliner is stained	
4	Exterior	Grille is loose with zip tie repair	
5	Utility box	Drivers side panels scratched and dented	
6	Exterior	Utility step bar damaged	
7	Engine	Pan is moist with oil residue but no obvious leak identified	
8	Fault code	SID 3 FMI 14 Wheel sensor ABS	

Photos



Videos

- Video 1
- Video 2
- Video 3
- Video 4

Files

- 3FRXF75627V515423_2026-10-21T14_15_33.pdf

This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, safety, or future performance.

© 2026 Beacon Inspection Services, All Rights Reserved
www.beaconinspection.com
(816) 607-9685