2015 FORD F750 | 3FRNF7FK1FV535229



Specifications

OD Miles:	66333	ECM Miles:	66367
Engine Hours:	6875	Engine Make:	Cummins
Engine Model:	ISB 6.7 CM250 B101	Engine Serial:	73757905
Engine HP:	200	Fuel Type:	Diesel
Fuel Tanks:	1 Alum	Fuel Capacity:	50
Exhaust:	Horizontal	Breathers:	Single
Trans Make:	Allison	Trans Type:	Auto
Trans Model:	3000 RDS	Trans Speed:	6
Trans Control:	Dash	Axle Qty:	3
Axle Type:	Single	Axle F Capacity:	13,020
Axle R Capacity:	21,000	GVWR:	33,000
Frame Type:	Steel	Suspension:	Spring
Wheelbase:	193	Brake Type:	Disc
Engine Brake:	Yes	Air Cond:	Yes
Interior Color:	grey	Exterior Color:	White
Heated Mirrors:	No	Power Mirrors:	Yes
High Back Seats:	Dual	Passenger Seat:	Stationary
Radio:	Dual	Bumper:	Chrome
Collision Avoidance:	No		

Tires, Wheels & Brakes - Front Axle

Left	Right
Tires/Wheels: Good Size: 11R 24.5 HEAT Steel	Tires/Wheels: Good Size: 11R 24.5 HEAT Steel
Brakes: Covered	Brakes: Covered

Tires, Wheels & Brakes - Rear Axles

Left Outer	Left Inner	Right Inner	Right Outer
Tires/Wheels: Good Size: 11R 24.5 HEAT Steel	Tires/Wheels: Good Size: 11R 24.5 HEAT Steel	Tires/Wheels: Good Size: 11R 24.5 HEAT Steel	Tires/Wheels: Good Size: 11R 24.5 HEAT Steel
Brakes: Covered	Brakes: Covered	Brakes: Covered	Brakes: Covered

Observations

Keys Present?	1 Sets	Oil Leaks?	Yes
Oil Milky?	No	Water Leaks?	No
Oil In Coolant?	No	Clutch Play?	NA
Starts?	Yes	Cracked/Chipped Glass?	No
Lights Works?	No	Wipers Works?	Yes
Gauges Works?	Yes	Air Horn Works?	Yes
City Horn Works?	Yes	Active Fault Codes	No

General Observation Notes

Front passenger side headlamp not working/out

Deficiencies

Issue #	Check	Comment	Photo
1	Front Headlamp not working	Passenger side	
2	Frozen lock on central cabinet door	Passenger side	
3	Gas tank mirror damage	dent	
4	PTO Disabled	Room and stabilizers inoperable	

Photos



Videos

Video 1

This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, agility, or future performance.

© 2025 Beacon Inspection Services, All Rights Reserved
www.beaconinspectionservices.com
(615) 627-4626