Beacon Inspection Solutions
Inspection #14289
11/09/2026

2015 BRINDLE CRT2 | 1L90R1828FG085326



Specifications

Axle Type	Tandem	Spread Axle	No
Axle F Capacity	8,000	Axle R Capacity	8,000
GVWR	17,000	Frame Type	Steel
Suspension	Spring	Lift Gate?	No
Ext W	96	Ext Len	16.0
Floor	Steel	Body	Steel
Exterior Color	Grey	Brake Type	Disc/Drum

Tires, Wheels & Brakes - Rear Axles

Left	Right
Tires/Wheels Good 215/75R17.5 24/32 Steel Brakes Covered	Tires/Wheels Fair 215/75R17.5 18/32 Steel Brakes Covered

Left	Right
Tires/Wheels Fair 215/75R17.5 17/32 Steel Brakes Covered	Tires/Wheels Fair 215/75R17.5 14/32 Steel Brakes Covered

Photos

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, safety, or future performance.

© 2026 Beacon Inspection Services, All Rights Reserved
www.beaconinspection.com
(816) 631-9685