
2013 AVANT 528 | 7026215



Specifications

Engine Hours	106	Engine Make	Kubota
Engine Model	D1105-E703	Engine Serial	1U11673
Engine HP	25	Fuel Type	Diesel
Fuel Tanks	1 Plastic	Fuel Capacity	8
Trans Model	Avant Hydrohive Hydrosta	Axle Type	Single
Wheelbase	38	Brake Type	Hydraulic
Air Cond	No	Interior Color	Gray
Int Type	Vinyl	Exterior Color	Green

Tires, Wheels & Brakes - Front Axle

Left	Right
Tires/Wheels Good 26*12.00*12	Tires/Wheels Good 26*12.00*12
Seal Good	Seal Good
Brakes Covered	Brakes Covered

Tires, Wheels & Brakes - Rear Axles

Left	Right
Tires/Wheels Good 26*12.00*12	Tires/Wheels Good 26*12.00*12
Seal Good Covered	Seal Good Covered

Observations

Keys Present?	1 Sets	Oil Leaks?	Yes
Oil Milky?	No	Water Leaks?	No
Oil in Coolant?	No	Starts?	No
Lights Works?	No	Wipers Works?	No
Gauges Works?	No	Active Fault Codes	Yes

General Observation Notes

Unit secured to trailer, battery dead. Location noted new battery required.

Deficiencies

Issue #	Check	Comment	Photo
1	Lights	Left side headlamp is cracked	
2	Exterior	Body panels broken at hardware attachments	
3	Exterior	Left side, rear body panel cracked	

Photos



This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, safety, or future performance.

© 2026 Beacon Inspection Services. All Rights Reserved
www.beaconinspection.com
(814) 631-9645