BEACON
VEHICLE & EQUIPMENT INSPECTIONS

Beacon Inspection Solutions
Inspection #14531
11/19/2026

2018 AMERA TRAIL GNDT16610-16E | 17YGN1620JB069009



Specifications

Axle Type	Tandem	Spread Axle	No
Axle F Capacity	8,000	Axle R Capacity	8,000
GVWR	16,000	Payload	10,050
Frame Type	Steel	Suspension	Spring
Rear D Type	Swing	Lift Gate?	No
Ext W	83	Ext Len	16.0
Floor	Steel	Body	Steel
Exterior Color	Green	Ramp	6ft
Brake Type	Electric		

Tires, Wheels & Brakes - Rear Axles

Left	Right
Tires/Wheels Poor 235/85R16 1/32 Steel Brakes Covered	Tires/Wheels Poor 235/85R16 3/32 Steel Brakes Covered

Left	Right
Tires/Wheels Fair 235/85R16 7/32 Steel Brakes Covered	Tires/Wheels Fair 235/85R16 8/32 Steel Brakes Covered

Deficiencies

Issue #	Check	Comment	Photo
D1	Impact Damage to rear	Rear light/reflection damaged	🖼

Photos

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

D1

This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, safety, or future performance.

© 2026 Beacon Inspection Services, All Rights Reserved
www.beaconinspection.com
(816) 631-9685